SCHOOL	DESCRIPTION	ESTIMATE	
Bacon Academy	Replace 2 Triple Duty Valves, Boiler Rm	$14,512	
Bacon Academy	Replace 2 Actuators for AHU G2 & G3	$4,603	
Bacon Academy	Replace Compressor in CU-B4	$19,565	
Bacon Academy	Replace Compressor in AHU-F1	$18,049	
Bacon Academy	Cabinet Unit Heater Tech Wing	$15,943	
Bacon Academy	Replace 3 Motors @ AHU- A1, B1 & B2	$9,714	
Bacon Academy	Repairs to AUH-A1	$9,995	
Bacon Academy	Replace Condenser Fan Motor CU-A1	$1,843	
Bacon Academy	Add Cooling to HV-2 & HV-3 Tech Wing	$95,446	
Bacon Academy	Replace AHU-4 (Coils and Condenser)	$193,303	
Total		$382,973	$382,973
Jack Jackter Intermidiate School	Convert Chiller 1 to R-407C Refrigerant	$17,517	
Jack Jackter Intermidiate School	Convert Chiller 2 to R-407C Refrigerant	$14,982	
Jack Jackter Intermidiate School	Replace Triple Duty Valve Pump 1	$5,615	
Jack Jackter Intermidiate School	Replace Triple Duty Valve Pump 1	$5,615	
Jack Jackter Intermidiate School	Replace Motor Protector Chiller 1 Circ 2	$3,461	
Jack Jackter Intermidiate School	Replace 2 Butterfly Valves Dual Temp Loop	$6,222	
Jack Jackter Intermidiate School	Replace Compressor Split System RM 23	$4,045	
Jack Jackter Intermidiate School	Repairs to 2 Exhaust Fans, EF14 and LRM	$3,172	
Jack Jackter Intermidiate School	Replace Draft Damper Control Boiler 1	$1,808	
Jack Jackter Intermidiate School	Test Chiller 1, Circuit 2 for Leaks	$4,064	
Jack Jackter Intermidiate School	Repairs to Boilers 1 & 2	$3,235	
Total		$69,736	$69,736
Colchester Elementary School	Replace AC5	$14,797	
Colchester Elementary School	Replace Circulating Pump Boiler 1	$4,784	
Colchester Elementary School	Replace Mixing Valve Radiant Heat PreK	$2,834	
Colchester Elementary School	Replace Heating Valve & Damper AHU-15	$4,824	
Colchester Elementary School	Repairs to AHU-1, AHU4, AHU7, AHU14	$6,449	
Total		$33,688	$33,688
GRAND TOTAL			**$486,397**